

**MICROCHIP****PIC32MX3XX/4XX**

PIC32MX3XX/4XX Rev. B3 Silicon Errata

The PIC32MX3XX/4XX devices (Rev. B3) you received conform functionally to the corresponding device data sheet (DS61143), except for the anomalies described in this silicon errata document.

Any data sheet clarification issues related to the PIC32MX3XX/4XX family would be described in a data sheet errata document and made available on the Microchip web site, www.microchip.com.

Silicon errata listed here pertain only to PIC32MX3XX/4XX family devices with the following Device/Revision IDs.

TABLE 1: PERTINENT DEVICE/REVISION IDS

Part Number	Device ID	Revision ID
PIC32MX460F512L	0x78	0x409
PIC32MX460F256L	0x74	0x409
PIC32MX440F128L	0x6C	0x409
PIC32MX440F256H	0x52	0x409
PIC32MX360F512L	0x38	0x409
PIC32MX360F256L	0x34	0x409
PIC32MX340F256H	0x12	0x409
PIC32MX320F128H	0x0A	0x409
PIC32MX320F128L	0x2A	0x409
PIC32MX320F064H	0x06	0x409
PIC32MX320F032H	0x02	0x409

The Device ID and Revision ID of a PIC32MX3XX/4XX Rev. B3 device can be confirmed by performing a "Reset and Connect" operation to the device using MPLAB® REAL ICE™ in-circuit emulator with MPLAB IDE, version 8.0 or later.

"Reset and Connect" requires that a device is specified by clicking *Configure>Select Device*. A message that includes the Device ID Revision number of the device is displayed in the **Output** window to indicate successful connection to the device.

A Device ID Revision number acquired by this method can be resolved to the data in Table 1 by splitting the number, as demonstrated by the following example:

"Device ID Revision = 40938000" yields the following IDs:

Device ID = 0x38
Revision ID = 0x409

The errata described in this section will be addressed in future revisions of silicon.

1. Module: Device Reset

A Reset (MCLR) Pulse that is shorter than 2 SYSCLK will not reset the device properly.

Work around

Ensure that the device is held in Reset for more than 2 SYSCLK to ensure proper device Reset operation.

2. Module: Device Reset

All Resets, except Power-On-Reset (POR), can cause a fail-safe clock monitor event (if enabled), when the duration of the Reset pulse exceeds the clock period of the internal fail-safe clock reference clock—31 kHz.

Work around

If long Reset pulses are anticipated, ignore or disable fail-safe clock monitor events.

3. Module: Software Device Reset

Attempting to perform a software device Reset with PBDIV set to 1:1 and SYSCLK less than 1 MHz will not reset the device properly.

Work around

Work around 1: Change PBDIV before performing a software Reset.

Work around 2: Set SYSCLK to a value that is greater than 1 MHz.

4. Module: External Voltage Regulator Mode

A VDDCORE voltage less than 1.75V will cause the CPU to reset when using an external core voltage supply.

Work around

Work around 1: Use the internal voltage regulator.

Work around 2: Use an external 1.8V regulator which has a regulation specification of <= 2.5%. The Microchip TC1055-1.8VCT713 Low Drop-Out regulator (LDO), or an equivalent, is recommended.

PICPIC32MX3XX/4XX

5. Module: ADC

When running the A/D converter in Internal Reference mode, the gain error is 3-4 LSb and the offset error is 1-2 LSb across voltage and speed.

Work around

Use in-system calibration and software techniques to compensate for these errors.

6. Module: Bus Matrix Registers

The BMXDUDBA, BMXDUPBA, and BMXPUPBA registers can be set to values that are outside of the device's actual memory-size limit.

Work around

Do not write values greater than the specified memory size of the device to the Bus Matrix registers. Ensure upper bits of the registers remain clear ('0').

7. Module: Clock Failure Event

After a clock failure event, any write to OSCCON erroneously clears fail-safe condition and attempts to switch to a new clock source that is specified by NOSC bits in OSCCON register.

Work around

After a clock failure event, do the following:

1. Write '000' to NOSC bits in OSCCON register to select the Fast RC oscillator. This will ensure that an erroneous clock switch selects the known good on-chip Fast RC oscillator.
2. Modify OSCCON register with any value your application requires.

8. Module: DMA Pattern Match Mode

In Pattern Match mode the DMA will generate up to 3 additional byte writes to the destination address—after the Pattern Detection event has occurred—when performing transfers with the DCHxSSIZ set to greater than 1.

Work around

Use one of the following three work-arounds:

Work around 1: The destination buffer needs to be large enough to accommodate the extra bytes (up to 3 extra bytes).

Work around 2: Set the destination size register to 1.

Work around 3: Set the source size register to 1.

9. Module: Output Compare in PWM Mode

The Output Compare module in PWM mode outputs a high of period register (PRx) length when attempting to use PWM values of 0x00 followed by a 0x01.

Work around

Do not use a PWM value of 0x01.

10. Module: Parallel Master Port (PMP)

In PMP Slave 4B Buffer mode, if underflow Status bit OBF (PMSTAT<6>) is cleared at the same time a PMP read is attempted, the PMP could get incorrect data.

Work around

The CPU can read the underflow flag OBUF and set/clear an I/O pin for the external master device to read. The state of the pin should indicate to the external master device that an underflow has occurred and no additional reads should occur until the underflow status has been cleared by the CPU.

11. Module: Ports

The SET/CLR/INV registers for port SFRs use latched value (LATCH) to perform single-cycle hardware read-modify-write operation.

Work around

Use one of the following two work-arounds:

Do not use SET/CLR/INV operations on a port if it contains one pin (or more) that are configured as a bidirectional digital pin.

Before performing SET/CLR/INV operations on a PORT containing a bidirectional digital pin, reset the corresponding LATCH bit to desired/fail-safe value.

12. Module: Timer1, 2, 3, 4, 5

TMRx register stays at zero for two timer clock cycles when the PRx register is 0x0000.

Work around

None.

13. Module: Timer1, 2, 3, 4, 5

Writes to SET/CLR/INV registers for TMRx and PRx produce incorrect results.

Work around

Use TMRx and PRx registers to manipulate bits.

14. Module: Timer1

Timer1 prescaler may not be reset correctly when it is used with a slow external clock. This can occur when the timer is disabled, and then re-enabled. The result could be a spurious count in the prescaler.

Work around

None.

15. Module: UART Hardware Handshake Mode

The CTS pin does not deassert until at least 2 bytes are free in the UART FIFO.

Work around

The UART TXREG must be read at least 2 times to rearm the hardware handshaking lines.

16. Module: Watchdog Timer (WDT)

An incorrect WDT Time-out Reset may occur when both of following conditions are present:

1. WDT is enabled.
2. Either a MCLR (EXTR) or Software Reset (SWR) occurs just before WDT is about to expire.

Work around

To detect incorrect WDT Time-out Reset, always confirm that only WDTO bit is set in RCON register. If EXTR, SWR, or any other Reset bits are set, it indicates that an incorrect WDT has occurred.

17. Module: DMA Channel Abort

DMA Channel Abort on a channel that is not currently active may have unintended effects on other active channels.

Work around

1. Suspend the channel, rather than abort, by clearing the channel enable bit DCHxCON<CHEN>.
2. Wait until other DMA channels complete before issuing the abort.

18. Module: Oscillator

The Primary Oscillator Circuit (POSC), when using XT/XTPPLL/HS/HSPLL modes, does not operate over the temperature range that is listed as item D5 in the device data sheet. Operation range without the workaround is limited to -40°C to +60°C.

Work around

Install a 4.1 M Ohm resistor in parallel with the crystal. This allows operation across the temperature range that is listed in the data sheet.

19. Module: PMP

The WAITE field in PMMODE<1:0> does not add a wait state to PMP Master reads when it is programmed to the value '01'. The WAITE field allows wait states to be added to the end of PMP read/write operations. This field is intended to add the following wait clocks after the read operation completes:

- 00 – no wait states
01 – 1 wait state
10 – 2 wait states
11 – 3 wait states

Current behavior is the following:

- 00 – no wait states
01 – no wait states
10 – 2 wait states
11 – 3 wait states

Work around

This erratum only applies to PMP Master read operations. PMP writes work correctly. Use another wait state control value that is allowed for the attached device.

PICPIC32MX3XX/4XX

APPENDIX A: REVISION HISTORY

Revision A (02/2008)

Initial release of this document.

Revision B (04/2008)

Oscillator temperature issue was added. Flash Program Memory 500ns delay requirement is now classified as architectural behavior. Added PMP WAITE behavior.

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, rfPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC³² logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rFLAB, Select Mode, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.



Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
=ISO/TS 16949:2002=**

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMS, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



MICROCHIP

WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara

Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533

Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471-6166
Fax: 81-45-471-6122

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820