



**MICROCHIP**

**PIC24HJXXXGPX06/X08/X10**

---

---

## PIC24HJXXXGPX06/X08/X10 Rev. A2/A3 Silicon Errata

---

---

The PIC24H (Rev. A2/A3) devices you received were found to conform to the specifications and functionality described in the following documents:

- DS70175 – “PIC24H Family Data Sheet”
- DS70157 – “dsPIC30F/33F Programmer’s Reference Manual”
- DS70046 – “dsPIC30F Family Reference Manual”

The exceptions to the specifications in the documents listed above are described in this section. The specific devices for which these exceptions are described are listed below:

- PIC24HJ64GP206
- PIC24HJ64GP210
- PIC24HJ64GP506
- PIC24HJ64GP510
- PIC24HJ128GP206
- PIC24HJ128GP210
- PIC24HJ128GP306
- PIC24HJ128GP310
- PIC24HJ128GP506
- PIC24HJ128GP510
- PIC24HJ256GP206
- PIC24HJ256GP210
- PIC24HJ256GP610

PIC24H Rev. A2/A3 silicon is identified by performing a “Reset and Connect” operation to the device using MPLAB<sup>®</sup> ICD 2 with MPLAB IDE v7.40 or later. The output window will show a successful connection to the device specified in *Configure>Select Device*. The resulting DEVREV register values for Rev. A2/A3 silicon are 0x3002 and 0x3004, respectively.

The errata described in this document will be addressed in future revisions of silicon.

### Silicon Errata Summary

The following list summarizes the errata described in further detail through the remainder of this document:

1. Doze Mode  
When Doze mode is enabled, any writes to a peripheral SFR can cause other updates to that register to cease to function for the duration of the current CPU clock cycle.
2. 12-bit Analog-to-Digital Converter (ADC) Module  
For this revision of silicon, the 12-bit ADC module INL, DNL and signal acquisition time parameters are not within the published data sheet specifications.
3. 10-bit ADC Module  
For this revision of silicon, the 10-bit ADC module DNL, conversion speed and signal acquisition time parameters are not within the published data sheet specifications.
4. DMA Module: Interaction with EXCH Instruction  
The EXCH instruction does not execute correctly when one of the operands contains a value equal to the address of the DMAC SFRs.
5. DISI Instruction  
The DISI instruction will not disable interrupts if a DISI instruction is executed in the same instruction cycle that the DISI counter decrements to zero.
6. Output Compare Module in PWM Mode  
The output compare module will miss one compare event when the duty cycle register value is updated from 0x0000 to 0x0001.
7. SPI Module in Frame Master Mode  
The SPI module will fail to generate frame synchronization pulses in Frame Master mode if FRMDLY = 1.
8. SPI Module in Slave Select Mode  
The SPI module Slave Select functionality will not work correctly.
9. SPI Module  
The SMP bit does not have any effect when the SPI module is configured for a 1:1 prescale factor in Master mode.

# PIC24HJXXXGPX06/X08/X10

---

10. ECAN™ Module  
ECAN transmissions may be incorrect if multiple transmit buffers are simultaneously queued for transmission.
11. ECAN Module  
Under specific conditions, the first five bits of a transmitted identifier may not match the value in the transmit buffer ID register.
12. ECAN Module Loopback Mode  
The ECAN module (ECAN1 or ECAN2) does not function correctly in Loopback mode.
13. I<sup>2</sup>C™ Module  
The Bus Collision Status bit does not get set when a bus collision occurs during a Restart or Stop event.
14. INT0, ADC and Sleep/Idle Mode  
ADC event triggers from the INT0 pin will not wake-up the device from Sleep or Idle mode if the SMPI bits are non-zero.
15. Doze Mode and Traps  
The address error trap, stack error trap, math error trap and DMA error trap will not wake-up a device from Doze mode.
16. JTAG Programming  
JTAG programming does not work.
17. UART  
With the parity option enabled, a parity error may occur if the Baud Rate Generator (BRG) contains an odd value.
18. UART  
The Receive Buffer Overrun Error Status bit may get set before the UART FIFO has overflowed.
19. UART  
UART receptions may be corrupted if the BRG is set up for 4x mode.
20. UART  
The UTXISEL0 bit is always read back as zero.
21. UART  
The auto-baud feature may not calculate the correct baud rate when the BRG is set up for 4x mode.
22. UART  
With the auto-baud feature selected, the sync break character (0x55) may be loaded into the FIFO as data.
23. I<sup>2</sup>C Module  
A write collision does not prevent the transmit register from being written.
24. I<sup>2</sup>C Module  
The ACKSTAT bit only reflects the received ACK/NACK status for Master transmissions, but not for Slave transmissions.
25. I<sup>2</sup>C Module  
The D\_A Status bit does not get set on a slave write to the transmit register.
26. Traps and Idle Mode  
If a clock failure occurs when the device is in Idle mode, the oscillator failure trap does not vector to the Trap Service Routine (TSR).
27. MCLR Wake-up from Sleep Mode  
An  $\overline{\text{MCLR}}$  wake-up from Sleep mode does not wait for the on-chip voltage regulator to power-up.
28. ECAN Module  
The C1RXOVF2 and C2RXOVF2 registers always read back as 0x0000.
29. FRC Oscillator  
Internal FRC accuracy parameters are not within the published data sheet specifications.
30. SPI Module  
SPI1 functionality for pin 34 (U1RX/SDI1/RF2) is erroneously enabled by the SPI2 module.
31. UART  
The auto-baud feature measures baud rate inaccurately for certain baud rate and clock speed combinations.
32. Device ID Register  
The content of the Device ID register changes from the factory programmed value.
33. DMA Module  
DMA data transfers that are active in Single-Shot mode while the device is in Sleep or Idle mode may result in more data transfers than expected.
34. Doze Mode and Traps  
A DMA error trap may not be generated when the device is in Doze mode.
35. ECAN Module  
If receive masking is disabled for a receive filter, the module behaves as if DeviceNet™ Addressing were enabled.
36. Output Compare Module  
In Dual Compare Match mode, the OCx output is not reset when the OCxR and OCxRS registers are loaded with values having a difference of 1.
37. UART  
When the UART is in 4x mode (BRGH = 1) and using two Stop bits (STSEL = 1), it may sample the first Stop bit instead of the second one.

- 38. UART  
When an auto-baud is detected, the receive interrupt may occur twice.
- 39. DMA  
NULL Data Peripheral Write mode for the DMA channel does not function.
- 40. DMA  
DMA request Fault condition does not generate a DMA error trap.
- 41. DMA  
DMA channel writes an additional NULL value to the peripheral register.
- 42. REPEAT Instruction  
Any instruction executed inside a REPEAT loop that produces a Read-After-Write stall condition, results in the instruction being executed fewer times than was intended.
- 43. FRC Oscillator  
For certain values of the TUN<5:0> bits (OSCTUN<5:0>), the resultant frequencies are incorrect.
- 44. UART Module  
The 16x baud clock signal on the BCLK pin is present only when the module is transmitting.
- 45. SPI Module  
The SP1xCON1 DISSCK bit does not influence port functionality.
- 46. I<sup>2</sup>C Module  
The BCL bit in I2CSTAT can be cleared only with 16-bit operation and can be corrupted with 1-bit or 8-bit operations on I2CSTAT.
- 47. I<sup>2</sup>C Module: 10-bit addressing mode  
When the I<sup>2</sup>C module is configured for 10-bit addressing using the same address bits (A10 and A9) as other I<sup>2</sup>C device A10 and A9 bits may not work as expected.

The following sections describe the errata and work around to these errata, where they may apply.

## 1. Module: Doze Mode

Enabling Doze mode slows down the CPU but allows peripherals to run at full speed. When the CPU clock is slowed down by enabling Doze mode (CLKDIV<11> = 1), any writes to a peripheral SFR can cause other updates to that register to cease to function for the duration of the current CPU clock cycle. This is only an issue if the CPU attempts to write to the same register as a peripheral while in Doze mode.

For instance, if the ADC module is active and Doze mode is enabled, the main program should avoid writing to ADCCONx registers because these registers are being used by the ADC module. If the CPU does make writes before the ADC module does, then any attempts by the ADC module to write to these registers will fail.

### **Work around**

In Doze mode, avoid writing code that will modify SFRs which may be written to by enabled peripherals.

# PIC24HJXXXGPX06/X08/X10

## 2. Module: 12-bit ADC

When the ADC module is configured for 12-bit operation, the specifications in the data sheets are not met.

### Work around

Implement the ADC module as an 11-bit ADC with a maximum conversion rate of 300 ksps.

1. The specifications in Table 1 reflect 11-bit ADC operation. RIN source impedance is recommended as 200 ohms and sample time is recommended as 3 TAD to ensure compatibility on future enhanced ADC modules. Missing codes are possible every  $2^7$  codes.
2. When used as a 10-bit ADC, the INL is  $<\pm 2$  Least Significant Bytes (LSBs), and DNL is  $<\pm 1$  LSB with no missing codes. Maximum conversion rate is 300 ksps.

**TABLE 1: ADC PERFORMANCE (11-BIT OPERATION)**

Param No.	Symbol	Min	Typical	Max	Units	Conditions
AD17	RIN	—	—	200	Ohm	12-bit
<b>ADC Accuracy – Measurements taken with External VREF+/VREF-</b>						
AD20a	Nr	—	12 bits	—	Bits	—
AD21a	INL	-2	—	2	LSB	—
AD22a	DNL	-1.5	—	1	LSB	—
AD23a	GERR	1	5	10	LSB	—
AD24a	EOFF	1	3	6	LSB	—
<b>ADC Accuracy – Measurements taken with Internal VREF+/VREF-</b>						
AD21aa	INL	-2	—	2	LSB	—
AD22aa	DNL	-1.5	—	1	LSB	—
AD23aa	GERR	5	10	20	LSB	—
AD24aa	EOFF	3	6	15	LSB	—
<b>Dynamic Performance</b>						
AD33a	FNYQ	—	—	150	KHz	—
AD34a	ENOB	9.5	9.6	10.4	Bits	—
<b>ADC Conversion Rate</b>						
AD56a	FCNV	—	—	300	ksps	—
AD57a	TSAMP	—	3 TAD	—	—	—

# PIC24HJXXXGPX06/X08/X10

## 3. Module: 10-bit ADC

When the ADC module is configured for 10-bit operation, the specifications in the data sheet are not met for operation above 500 ksps.

For 500 ksps, the module meets specifications except for Gain and Offset parameters AD23bb and AD24bb.

For 600 ksps operation, the module specifications are shown in Table 2.

### **Work around**

None. Future versions of the silicon will support the ADC performance stated in the data sheet.

**TABLE 2: 600 KSPS OPERATION**

Param No.	Symbol	Min	Typical	Max	Units	Conditions
AD17	RIN	—	—	200	Ohm	10-bit
<b>ADC Accuracy – Measurements taken with External VREF+/VREF-</b>						
AD20b	Nr	—	10 bits	—	Bits	—
AD21b	INL	-2	—	2	LSB	—
AD22b	DNL	-1.5	—	2	LSB	—
AD23b	GERR	1	3	6	LSB	—
AD24b	EOFF	1	2	5	LSB	—
<b>ADC Accuracy – Measurements taken with Internal VREF+/VREF-</b>						
AD21bb	INL	-2	—	2	LSB	—
AD22bb	DNL	-1.5	—	2	LSB	—
AD23bb	GERR	1	6	12	LSB	—
AD24bb	EOFF	2	5	10	LSB	—
<b>Dynamic Performance</b>						
AD33b	FNYQ	—	—	300	KHz	—
AD34b	ENOB	8.5	9.7	9.8	Bits	—
<b>ADC Conversion Rate</b>						
AD56b	FCNV	—	—	600	ksps	—
AD57b	TSAMP	—	3 TAD	—	—	—

# PIC24HJXXXGPX06/X08/X10

---

## 4. Module: DMA Module: Interaction with EXCH Instruction

The EXCH instruction does not execute correctly when either of the two operands is numerically equal to the address of any of the DMAC SFRs for this revision of silicon.

### **Work around**

If writing source code in assembly, the recommended fix is to replace:

```
EXCH Wsource, Wdestination
```

with:

```
PUSH Wdestination
```

```
MOV Wsource, Wdestination
```

```
POP Wsource
```

If using the MPLAB C30 C compiler, specify the compiler option, `-merrata=exch` (*Project>Build Options>Projects>MPLAB C30>Use Alternate Settings*)

## 5. Module: DISI Instruction

When a user executes a DISI #7, for example, this will disable interrupts for 7 + 1 cycles (7 + the DISI instruction itself). In this case, the DISI instruction uses a counter which counts down from 7 to 0. The counter is loaded with 7 at the end of the DISI instruction.

If the user code executes another DISI on the instruction cycle where the DISI counter has become zero, the new DISI count is loaded, but the DISI state machine does not properly re-engage and continue to disable interrupts. At this point, all interrupts are enabled. The next time the user code executes a DISI instruction, the feature will act normally and block interrupts.

In summary, it is only when a DISI execution is coincident with the current DISI count = 0, that the issue occurs. Executing a DISI instruction before the DISI counter reaches zero will not produce this error. In this case, the DISI counter is loaded with the new value, and interrupts remain disabled until the counter becomes zero.

### **Work around**

When executing multiple DISI instructions within the source code, make sure that subsequent DISI instructions have at least one instruction cycle between the time that the DISI counter decrements to zero and the next DISI instruction. Alternatively, make sure that subsequent DISI instructions are called before the DISI counter decrements to zero.

## 6. Module: Output Compare Module in PWM Mode

The output compare module will miss a compare event when the current duty cycle register (OCxRS) value is 0x0000 (0% duty cycle), and the OCxRS register is updated with a value of 0x0001. The compare event is only missed the first time a value of 0x0001 is written to OCxRS, and the PWM output remains low for one PWM period. Subsequent PWM high and low times occur as expected.

### **Work around**

None. If the current OCxRS register value is 0x0000, avoid writing a value of 0x0001 to OCxRS. Instead, write a value of 0x0002; however, in this case the duty cycle will be slightly different from the desired value.

## 7. Module: SPI Module in Frame Master Mode

The SPI module will fail to generate frame synchronization pulses when configured in the Frame Master mode if the start of data is selected to coincide with the start of the frame synchronization pulse (FRMEN = 1, SPIFSD = 0, FRMDLY = 1). However, the module functions correctly in Frame Slave mode, and also in Frame Maser mode if FRMDLY = 0.

### **Work around**

If DMA is not being used, manually drive the  $\overline{SS}_x$  pin (x = 1 or 2) high using the associated PORT register, and then drive it low after the required 1 bit-time pulse-width. This operation needs to be performed when the transmit buffer is written.

If DMA is being used, and if no other peripheral modules are using DMA transfers, use a Timer interrupt to periodically generate the frame synchronization pulse (using the method described above) after every 8- or 16-bit periods (depending on the data word size, configured using the MODE 16-bit).

If FRMDLY = 0, no work around is needed.

## 8. Module: SPI Module in Slave Select Mode

The SPI module Slave Select functionality (enabled by setting  $\overline{\text{SSEN}} = 1$ ) will not function correctly. Whether the  $\overline{\text{SSx}}$  pin ( $x = 1$  or  $2$ ) is high or low, the SPI data transfer will be completed and an interrupt will be generated.

### Work around

If DMA is not being used, manually poll the  $\overline{\text{SSx}}$  pin state in the SPI interrupt by reading the associated LAT bit:

- If the LAT bit is '0', then perform the required data read/write.
- If the LAT bit is '1', then clear the SPI interrupt flag (SPIXIF), perform a dummy read of the SPIXBUF register and return from the Interrupt Service Routine (ISR).

If DMA is being used, there is no work around.

## 9. Module: SPI Module

The SMP bit (SPIxCON1<9>, where  $x = 1$  or  $2$ ) does not have any effect when the SPI module is configured for a 1:1 prescale factor in Master mode. In this mode, whether the SMP bit is set or cleared, the data is always sampled at the end of data output time.

### Work around

If sampling at the middle of data output time is required, then configure the SPI module to use a clock prescale factor other than 1:1 using the PPRE<1:0> and SPRE<2:0> bits in the SPIxCON1 register.

## 10. Module: ECAN Module

If multiple ECAN transmit buffers are enabled (multiple TXREQ or TXEN bits are set to '1' simultaneously), then the message transmissions from the enabled buffers may interfere with one another. As a result, incorrect ID and data transmissions will occur intermittently.

### Work around

Enable only Buffer 0 for transmission at any given time. In the user application, this can be ensured by checking that all other TXREQn and TXENn bits are clear, before setting the TXREQn bit or TXENn to Buffer 0.

## 11. Module: ECAN Module

Under specific conditions, the first five bits of a transmitted identifier may not match the value in the transmit buffer SID. If the ECAN module detects a Start-of-Frame (SOF) in the third bit of interframe space and if a message to be transmitted is pending, the first five bits of the transmitted identifier may be corrupted.

### Work around

None.

## 12. Module: ECAN Module Loopback Mode

The ECAN module (ECAN1 or ECAN2) does not function correctly in Loopback mode.

### Work around

Do not use Loopback mode.

## 13. Module: I<sup>2</sup>C Module

The Bus Collision Status bit (BCL) does not get set when a bus collision occurs during a Restart or Stop event. However, the BCL bit gets set when a bus collision occurs during a Start event.

### Work around

None.

## 14. Module: INT0, ADC and Sleep/Idle Mode

ADC event triggers from the INT0 pin will not wake-up the device from Sleep or Idle mode if the SMPI bits are non-zero. This means that if the ADC is configured to generate an interrupt after a certain number of INT0 triggered conversions, the ADC conversions will not be triggered and the device will remain in Sleep. The ADC will perform conversions and wake-up the device only if it is configured to generate an interrupt after each INT0 triggered conversion (SMPI<3:0> = 0000).

### Work around

None. If ADC event trigger from the INT0 pin is required, initialize SMPI<3:0> to '0000' (interrupt on every conversion).

## 15. Module: Doze Mode and Traps

The address error trap, stack error trap, math error trap and DMA error trap will not wake-up a device from Doze mode.

### Work around

None.

# PIC24HJXXXGPX06/X08/X10

---

## 16. Module: JTAG Programming

JTAG programming does not work.

### Work around

None.

## 17. Module: UART

With the parity option enabled, a parity error, indicated by the PERR bit (UxSTA<3>) being set, may occur if the Baud Rate Generator contains an odd value. This affects both even and odd parity options.

### Work around

Load the Baud Rate Generator register, UxBRG, with an even value, or disable the peripheral's parity option by loading either 0b00 or 0b11 into the Parity and Data Selection bits, PDSEL<1:0> (UxMODE<2:1>).

## 18. Module: UART

The Receive Buffer Overrun Error Status bit, OERR (UxSTA<1>), may get set before the UART FIFO has overflowed. After the fourth byte is received by the UART, the FIFO is full. The OERR bit should set after the fifth byte has been received in the UART shift register. Instead, the OERR bit may set after the fourth received byte with the UART Shift register empty.

### Work around

After four bytes have been received by the UART, the UART Receiver Interrupt Flag bit, U1RXIF (IFS0<11>) or U2RXIF (IFS1<14>), will be set, indicating the UART FIFO is full. The OERR bit may also be set. After reading the UART receive buffer, UxRXREG, four times to clear the FIFO, clear both the OERR and UxRXIF bits in software.

## 19. Module: UART

UART receptions may be corrupted if the Baud Rate Generator is set up for 4x mode (BRGH = 1).

### Work around

Use the 16x baud rate option (BRGH = 0) and adjust the baud rate accordingly.

## 20. Module: UART

The UTXISEL0 bit (UxSTA<13>) is always read as zero regardless of the value written to it. The bit can be written to either a '0' or '1', but will always be read as zero. This will affect read-modify-write operations such as bitwise or shift operations. Using a read-modify-write instruction on the UxSTA register (e.g., BSET, BLCR) will always write the UTXISEL0 bit to zero.

### Work around

If a UTXISEL0 value of '1' is needed, avoid using read-modify-write instructions on the UxSTA register. Copy the UxSTA register to a temporary variable and set UxSTA<13> prior to performing read-modify-write operations. Copy the new value back to the UxSTA register.

## 21. Module: UART

The auto-baud feature may not calculate the correct baud rate when the High Baud Rate Enable bit, BRGH, is set. With the BRGH bit set, the baud rate calculation used is the same as BRG = 0.

### Work around

If the auto-baud feature is needed, use the Low Baud Rate mode by clearing the BRGH bit.

## 22. Module: UART

With the auto-baud feature selected, the sync break character (0x55) may be loaded into the FIFO as data.

### Work around

To prevent the sync break character from being loaded into the FIFO, load the UxBRG register with either 0x0000 or 0xFFFF prior to enabling the auto-baud feature (ABAUD = 1).



## 23. Module: I<sup>2</sup>C Module

Writing to I2CxTRN during a Start bit transmission generates a write collision, indicated by the IWCOL (I2CxSTAT<7>) bit being set. In this state, additional writes to the I2CxTRN register should be blocked. However, in this condition, the I2CxTRN register can be written, although transmissions will not occur until the IWCOL bit is cleared in software.

### Work around

After each write to the I2CxTRN register, read the IWCOL bit to ensure a collision has not occurred. If the IWCOL bit is set, it must be cleared in software and I2CxTRN register must be rewritten.

## 24. Module: I<sup>2</sup>C Module

The ACKSTAT bit (I2CxSTAT<15>) only reflects the received ACK/NACK status for Master transmissions, but not for Slave transmissions. As a result, a Slave cannot use this bit to determine if it received an ACK or a NACK from a Master. In future silicon revisions, the ACKSTAT bit will reflect received ACK/NACK status for both Master and Slave transmissions.

### Work around

After transmitting a byte, the Slave should poll the SDA line (subject to a time out period dependent on the application) to determine if an ACK ('0') or a NACK ('1') was received.

## 25. Module: I<sup>2</sup>C Module

The D\_A Status bit (I2CxSTAT<5>) gets set on a slave data reception in the I2CxRCV register, but does not get set on a slave write to the I2CxTRN register. In future silicon revisions, the D\_A bit will get set on a slave write to the I2CxTRN register.

### Work around

Use the D\_A Status bit only for determining slave reception status and not slave transmission status.

## 26. Module: Traps and Idle Mode

If a clock failure occurs when the device is in Idle mode, the oscillator failure trap does not vector to the Trap Service Routine. Instead, the device will simply wake-up from Idle mode and continue code execution if the Fail-Safe Clock Monitor (FSCM) is enabled.

### Work around

Whenever the device wakes up from Idle (assuming the FSCM is enabled) the user software should check the state of the OSCFAIL bit (INTCON1<1>) to determine whether a clock failure occurred, and then perform the appropriate clock switch operation. Regardless, the Trap Service Routine must be included in the user application.

## 27. Module: $\overline{\text{MCLR}}$ Wake-up from Sleep Mode

If a  $\overline{\text{MCLR}}$  reset pulse causes the device to wake-up from Sleep mode, the device wakes up without waiting for the on-chip voltage regulator to power-up. This will subsequently result in a Brown-out Reset (BOR).

### Work around

None.

## 28. Module: ECAN Module

The C1RXOVF2 and C2RXOVF2 registers are non-functional. They are always read back as 0x0000, even when a receive overflow has occurred.

### Work around

None.

## 29. Module: FRC Oscillator

The device does not meet the internal FRC accuracy specifications in the data sheet (Table 23-18 of the "PIC24H Family Data Sheet" (DS70175)). The actual accuracy specifications are shown in Table 3.

### Work around

None.

**TABLE 3: INTERNAL FRC ACCURACY**

AC Characteristics		Standard Operating Conditions: 3.0V to 3.6V (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq \text{TA} \leq +85^{\circ}\text{C}$ for industrial				
Parameter No.	Characteristic	Min	Typical	Max	Units	Conditions
<b>Internal FRC Accuracy @ FRC Frequency = 7.37 MHz<sup>(1,2)</sup></b>						
F20	—	-3	—	+3	%	$-40^{\circ}\text{C} \leq \text{TA} \leq +85^{\circ}\text{C}$ VDD = 3.0-3.6V

**Note 1:** Frequency calibrated at 25°C and 3.3V. TUN bits can be used to compensate for temperature drift.

**2:** Devices set to initial frequency of 7.37 MHz ( $\pm 2\%$ ) at 25°C.

# PIC24HJXXXGPX06/X08/X10

---

## 30. Module: SPI Module

SPI1 functionality for pin 34 (U1RX/SDI1/RF2) is enabled by the SPI2 module. As a result, two side effects occur:

1. RF2 functionality is disabled if the SPI2 module is enabled.
2. This pin will not function as SDI1 if the SPI1 module is enabled.

This issue affects 64-pin devices only:

- PIC24HJ64GP206
- PIC24HJ128GP206
- PIC24HJ256GP206
- PIC24HJ128GP306
- PIC24HJ64GP506
- PIC24HJ128GP506

### Work around

Two conditions apply:

1. If the SPI2 module is used, pin 34 cannot be used as an I/O (RF2). It is recommended to use another I/O pin.
2. If the SPI1 module is used, the SPI2 module must also be enabled to gain SDI1 functionality on pin 34. As an alternative, I/O (RF2) can be configured as an input, which will allow pin 34 to function as SDI1.

## 31. Module: UART

The auto-baud feature may miscalculate for certain baud rate and clock speed combinations, resulting in a BRG value that is greater than or less than the expected value by 1. This may result in reception or transmission failures.

### Work around

Test the auto-baud rate at various clock speed and baud rate combinations that would be used in an application. If an inaccurate BRG value is generated, manually correct the baud rate in user software.

## 32. Module: Device ID Register

On a few devices, the content of the Device ID register can change from the factory programmed default value immediately after RTSP or ICSP™ Flash programming.

As a result, development tools will not recognize these devices and will generate an error message indicating that the device ID and the device part number do not match. Additionally, some peripherals will be reconfigured and will not function as described in the device data sheet.

Refer to **Section 5. “Flash Programming”** (DS70191), of the *“dsPIC33F Family Reference Manual”* for an explanation of RTSP and ICSP Flash programming.

### Work around

All RTSP and ICSP Flash programming routines must be modified as follows:

1. No word programming is allowed. Any word programming must be replaced with row programming.
2. During row programming, load write latches as described in **5.4.2.3 “Loading Write Latches”** of **Section 5. “Flash Programming”** (DS70191).
3. After latches are loaded, reload any latch location (in a given row) that has 5 LSB set to 0x18, with the original data. For example, reload one of the following latch locations with the desired data:  
0xFFFF18, 0xFFFF38, 0xFFFF58,  
0xFFFF78, 0xFFFF98, 0xFFFFB8,  
0xFFFFD8, 0xFFFFF8
4. Start row programming by setting NVMOP<3:0> = ‘0001’ (memory row program operation) in the NVMCON register.
5. After row programming is complete, verify the contents of Flash memory.
6. If Flash verification errors are found, repeat steps 2 through 5. If Flash verification errors are found after a second iteration, report this problem to Microchip.

Steps 1 through 5 in the work around are implemented in MPLAB IDE version 8.00 or higher for the MPLAB ICD 2, MPLAB REAL ICE™ in-circuit emulator and PM3 tools.

## 33. Module: DMA

When a DMA channel is enabled in Single-Shot mode while the device is in Idle mode, and the corresponding peripheral is active and configured to operate during Idle mode, the DMA channel may not become disabled immediately upon transferring the required amount of data.

As a result, the number of bytes or words of data transferred may exceed the DMA transfer count specified in the DMAxCNT register.

For example, if DMA transfers are active for both SPI byte transmissions and receptions, and only the receive DMA channel interrupt is enabled for waking up the device from Idle mode, an extra byte will be transmitted by the time the device wakes up from Idle mode.

### Work around

None.

## 34. Module: Doze Mode and Traps

A DMA error trap may not be generated when the device is in Doze mode.

### Work around

None.

## 35. Module: ECAN Module

If receive masking is disabled for any receive filter 'n' (n = 0, 1, 2, ..., 14) by setting the corresponding Mask Source Select (FnMSK<1:0>) bits to '11', the ECAN module behaves as if it were configured for DeviceNet Addressing. In this case, bit 7 of Byte 0 of every incoming message is compared with EID<17> of the Receive Filter, and desired messages may not be received as a result.

### Work around

To avoid this issue, do not disable receive masking for a filter 'n' by setting the FnMSK<1:0> bits. Instead, select any receive mask by configuring FnMSK<1:0> = 10, 01 or 00, and then disable the individual mask bits by clearing the SID<10:0> and EID<17:0> bits in the CiRXMnSID and CiRXMnEID registers (l = 1 or 2, and n = 0, 1 or 2).

## 36. Module: Output Compare Module

When the Output Compare Module is operated in the Dual Compare Match mode, a timer compare match with the value in the OCxR register sets the OCx output producing a rising edge on the OCx pin. Then, when a timer compare match with the value in the OCxRS register occurs, the OCx output is reset producing a falling edge on the OCx pin.

The above statement applies to all conditions except when the difference between OCxR and OCxRS is 1. In this case, the Output Compare module may miss the reset compare event, and cause the OCx pin to remain continuously high. This condition will remain until the difference between values in the OCxR and OCxRS registers is made greater than 1.

### Work around

Ensure in software that the difference between values in OCxR and OCxRS registers is maintained greater than 1.

## 37. Module: UART

When the UART is in 4x mode (BRGH = 1) and using two Stop bits (STSEL = 1), it may sample the first Stop bit instead of the second one.

This issue does not affect the other UART configurations.

### Work around

Use the 16x baud rate option (BRGH = 0) and adjust the baud rate accordingly.

## 38. Module: UART

When an auto-baud is detected, the receive interrupt may occur twice. The first interrupt occurs at the beginning of the Start bit and the second after reception of the Sync field character.

### Work around

If an extra interrupt is detected, ignore the additional interrupt.

# PIC24HJXXXGPX06/X08/X10

---

## 39. Module: DMA

When the DMA channel is configured for NULL Data Peripheral Write mode (DMAxCON<11> = 1), it does not execute a null (all zeros) write to the peripheral address.

### Work around

Use two DMA channels to receive data from the peripheral module. One channel must be configured to transfer data from the peripheral to DMA RAM, while another channel must be configured to transfer dummy data from the DMA RAM to the peripheral. Both channels must be setup for the same DMA request.

## 40. Module: DMA

A low priority DMA channel request can be pre-empted by a higher priority DMA channel request. For example, if DMA Channel 0 has a higher priority than DMA Channel 1. A request to DMA channel 1 will be pending while DMA Channel 0 is processing its request. If DMA Channel 1 receives another request while it is in a pending request state, the DMA module does not generate a DMA error trap event.

### Work around

None. Using higher priority DMA channels for servicing sources of frequent requests significantly reduces the possibility of the condition described above occurring, but does not completely eliminate it.

## 41. Module: DMA

When the DMA channel is configured for One Shot mode with NULL write enabled, the channel will write an extra NULL to the peripheral register after completing the last transfer. In the case of the SPI module and the SPIxBUF register, this would cause the SPI module to perform an extra receive operation.

### Work around

None. In the case of using DMA NULL write with the SPI module, perform a dummy read of the SPIxBUF register after the DMA transfer is completed to clear the SPIRBF flag and prevent an un-expected overflow condition on the next SPI receive operation.

## 42. Module: REPEAT Instruction

Any instruction executed inside a REPEAT loop, which produces a Read-After-Write stall condition, results in the instruction being executed fewer times than was intended.

An example of such code is:

```
repeat #0xf
inc [w1],[++w1]
```

### Work around

Avoid repeating an instruction that creates a stall using a REPEAT instruction. Instead, use a software loop using conditional branches.

# PIC24HJXXXGPX06/X08/X10

## 43. Module: FRC Oscillator

For certain values of the TUN<5:0> bits (OSCTUN<5:0>), the resultant frequencies do not match the expected values.

As shown in Table 4, the actual frequencies obtained for different values of the TUN<5:0> bits are listed in terms of percentage change relative to the center frequency of 7.3728 MHz. The frequency errors listed in the table are approximate and may vary slightly from device to device.

It is recommended that the user application include some means of measuring the exact oscillator frequency in order to verify the frequencies listed below.

### Work around

Configure your peripherals and other system parameters based on the actual frequencies listed in Table 4.

TABLE 4:

TUN<5:0>	Expected Change from 7.3728 MHz	Actual Change from 7.3728 MHz
000000	—	—
000001	+0.375%	+0.375%
000010	+0.75%	+0.75%
000011	+1.125%	+1.125%
000100	+1.5%	+1.5%
000101	+1.875%	+1.875%
000110	+2.25%	+2.25%
000111	+2.625%	+2.625%
001000	+3%	+3%
001001	+3.375%	+3.375%
001010	+3.75%	+3.75%
001011	+4.125%	+4.125%
001100	+4.5%	+4.5%
001101	+4.875%	+4.875%
001110	+5.25%	+5.25%
001111	+5.625%	+5.625%
010000	+6%	+8.325%
010001	+6.375%	+8.7%
010010	+6.75%	+9.075%
010011	+7.125%	+9.45%
010100	+7.5%	+9.825%
010101	+7.875%	+10.2%
010110	+8.25%	+10.575%
010111	+8.625%	+10.95%
011000	+9%	+11.325%
011001	+9.375%	+11.7%
011010	+9.75%	+12.075%
011011	+10.125%	+12.45%
011100	+10.5%	+12.825%
011101	+10.875%	+13.2%
011110	+11.25%	+13.575%
011111	+11.625%	+13.95%

TABLE 4: (CONTINUED)

TUN<5:0>	Expected Change from 7.3728 MHz	Actual Change from 7.3728 MHz
100000	-12%	-12%
100001	-11.625%	-11.625%
100010	-11.25%	-11.25%
100011	-10.875%	-10.875%
100100	-10.5%	-10.5%
100101	-10.125%	-10.125%
100110	-9.75%	-9.75%
100111	-9.375%	-9.375%
101000	-9%	-9%
101001	-8.625%	-8.625%
101010	-8.25%	-8.25%
101011	-7.875%	-7.875%
101100	-7.5%	-7.5%
101101	-7.125%	-7.125%
101110	-6.75%	-6.75%
101111	-6.375%	-6.375%
110000	-6%	-3.675%
110001	-5.625%	-3.3%
110010	-5.25%	-2.925%
110011	-4.875%	-2.55%
110100	-4.5%	-2.175%
110101	-4.125%	-1.8%
110110	-3.75%	-1.425%
110111	-3.375%	-1.05%
111000	-3%	-0.675%
111001	-2.625%	-0.3%
111010	-2.25%	+0.075%
111011	-1.875%	+0.45%
111100	-1.5%	+0.825%
111101	-1.125%	+1.2%
111110	-0.75%	+1.575%
111111	-0.375%	+1.95%

# PIC24HJXXXGPX06/X08/X10

---

## 44. Module: UART

When the UART is configured for IR interface operations ( $UxMODE\langle 9:8 \rangle = 11$ ), the 16x baud clock signal on the BCLK pin is present only when the module is transmitting. The pin is idle at all other times.

### **Work around**

Configure one of the output compare modules to generate the required baud clock signal when the UART is receiving data or in an idle state.

## 45. Module: SPI Module

Setting the DISSCK bit in the SPIxCON1 register does not allow the user application to use the SCK pin as a general purpose I/O pin.

### **Work around**

None.

## 46. Module: I<sup>2</sup>C Module

The BCL bit in I2CSTAT can be cleared only with 16-bit operation and can be corrupted with 1-bit or 8-bit operations on I2CSTAT.

### **Work around**

Use 16-bit operations to clear BCL.

## 47. Module: I<sup>2</sup>C Module

If there are two I<sup>2</sup>C devices on the bus, one of them is acting as the Master receiver and the other as the Slave transmitter. Suppose that both devices are configured for 10-bit addressing mode, and have the same value in the A10 and A9 bits of their addresses. When the Slave select address is sent from the Master, both the Master and Slave acknowledges it. When the Master sends out the read operation, both the Master and the Slave enter into Read mode and both of them transmit the data. The resultant data will be the ANDing of the two transmissions.

### **Work around**

Use different addresses including the higher two bits (A10 and A9) for different modules.

## APPENDIX A: REVISION HISTORY

### Revision A (6/2006)

Initial release of the document.

### Revision B (12/2006)

Added issues 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, and 17.

### Revision C (3/2007)

Changed document title, updated issue 8, and added issues 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30 and 31.

### Revision D (6/2007)

Added the following silicon issues: 32 (SPI Module), 33 (UART), 34 (Device ID Register), 35 (DMA), 36 (Doze Mode and Traps) and 37 (DCI).

### Revision E (10/2007)

Removed issue 6 (Output Compare Module) and issue 37 (DCI). Updated silicon issue 27 (Traps and Idle Mode). Added silicon issues 36 (ECAN Module), 37 (Output Compare Module), 38-39 (UART), 40-42 (DMA), 43 (REPEAT Instruction), and 44 (FRC Oscillator).

### Revision F (4/2008)

Updated silicon issues 4 (DMA Module: Interaction with EXCH Instruction) 10 (ECAN Module). Removed silicon issue 23 (ECAN). Added silicon issues 44 (UART), 45 (SPI Module) and 46-47 (I2C Module).

# PIC24HJXXXGPX06/X08/X10

---

NOTES:



---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

**Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, rPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC<sup>32</sup> logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rLAB, Select Mode, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
== ISO/TS 16949:2002 ==**

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



---

---

## Worldwide Sales and Service

---

---

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**  
Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**  
Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-4182-8400  
Fax: 91-80-4182-8422

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471- 6166  
Fax: 81-45-471-6122

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-572-9526  
Fax: 886-3-572-6459

**Taiwan - Kaohsiung**  
Tel: 886-7-536-4818  
Fax: 886-7-536-4803

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820