

MSP430FG42x0 Device Erratasheet

Current Version

| Devices | Rev: | CPU4 | DAC2 | DAC3 | FLL3 | LCDA1 | LCDA2 | LCDA3 | PORT6 | SDA1 | SDA3 | TA12 | TA16 | WDG2 |
|--------------|------|------|------|------|------|-------|-------|-------|-------|------|------|------|------|------|
| MSP430FG4250 | A | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| MSP430FG4260 | A | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| MSP430FG4270 | A | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |

Note: See Appendix for prior revisions

Package Markings

RGZ48: QFN(RGZ) 48-pin

○ MSP430
Fxxxx
TI YMS #
LLLLG4

YM = Year and Month Date Code
LLLL = LOT Trace Code
S = Assembly Site Code
= DIE Revision
o = PIN 1

○ M430
Fxxxx
TI YMS #
LLLLG4

YM = Year and Month Date Code
LLLL = LOT Trace Code
S = Assembly Site Code
= DIE Revision
o = PIN 1

DL48: SOP(DL) 48-pin

 YMLLLLS G4
M430Fxxxx
REV #
○

YM = Year and Month Date Code
LLLL = LOT Trace Code
S = Assembly Site Code
= DIE Revision
o = PIN 1

Detailed Bug Description

CPU4 CPU4 - Bug description:

Module: CPU, Function: PUSH #4, PUSH #8

The single operand instruction PUSH cannot use the internal constants (CG) 4 and 8. The other internal constants (0, 1, 2, -1) can be used. The Assembler version 1.08 and higher produces correct code. The number of clock cycles is different:

PUSH #CG uses address mode 00, requiring 3 cycles, 1 word instruction

PUSH #4/#8 uses address mode 11, requiring 5 cycles, 2 word instruction

Workaround implemented in assembler.

No fix planned.


Detailed Bug Description (continued)

DAC2 DAC2 - Bug description:

Module: DAC12, Function: P1.4 GPIO function is not disabled when P1.4 = DAC0 output

The DAC12OPS control bit used to automatically disable the P1.4 I/O logic is inverted as shown in the figure below. When DAC12 is enabled (DAC12AMPx > 0) and DAC12OPS=0, the port I/O for P1.4 will be disabled. Setting DAC12OPS = 1 to connect the DAC12 output to P1.4 will erroneously enable the port GPIO logic.

Port P1 pin schematic: P1.4, input/output with Schmitt-trigger and analog functions



Note: x = 4

Workaround:

The P1.4 I/O logic should be disabled when the DAC12 is enabled using the SD16AE.4 analog enable bit. SD16AE.4=1 will disable the P1.4 I/O logic. The A3 SD16_A analog input cannot be used under this condition.

Detailed Bug Description (continued)

DAC3 DAC3 - Bug description:

Module: DAC12, Function: Port P1.4 can not be used if DAC12 is internally enabled.

When DAC12 is enabled ($DAC12AMPx > 0$) and internal use is selected ($DAC12OPS=0$), the P1.4 digital I/O functionality is disabled.

See also: DAC2 bug description.

Workaround:

None

FLL3 FLL3 – Bug description:

Module: FLL+, Function: $FLLDx = 11$ for /8 may generate an unstable MCLK frequency

When setting the FLL to higher frequencies using $FLLDx = 11$ (/8) the output frequency of the FLL may have a larger frequency variation (e.g. averaged over 2sec) as well as a lower average output frequency than expected when compared to the other $FLLDx$ bit settings.

Workaround:

None

LCDA1 LCDA1 - Bug description:

Module: LCD_A, Function High voltage on LCD_A pins.

When static LCD mode is selected, the charge pump does not work correctly.

The feedback loop within the charge pump is switched off. This can result in high voltages on LCD_A segment and common pins.

WARNING: Using the charge pump when static mode is selected may cause permanent damage to the MSP430 device and/or the LCD.

Workaround:

None

LCDA2 LCDA2 - Bug description:

Module: LCD_A, Floating segment S5

Dedicated LCD segment S5 is floating when LCD_A is disabled: $LCDON = 0$.

In this case S5 should be connected to ground.

Workaround:

None

Detailed Bug Description (continued)

LCDA3 LCD A3 - Bug description:

Module: LCD_A, Charge pump voltage

The charge pump output voltage has an offset of approximately -200 mV. This reduces the LCD voltage levels specified in the datasheet for LCD_A by the same amount and should be accounted for when selecting a charge pump voltage. See actual values below:

LCD_A

| PARAMETER | | TEST CONDITIONS | VCC | MIN | TYP | MAX | UNIT |
|----------------------|----------------------------------|--|-------|------|------|------|------|
| V _{CC(LCD)} | Supply Voltage Range | Charge pump enabled (LCDCPEN = 1; VLCDx > 0000) | | 2.2 | | 3.6 | V |
| C _{LCD} | Capacitor on LCDCAP (see Note 1) | Charge pump enabled (LCDCPEN = 1; VLCDx > 0000) | | 4.7 | | | μF |
| I _{CC(LCD)} | Supply Current | V _{LCD(typ)} =3V; LCDCPEN = 1; VLCDx = 1000, all segments on f _{LCD} = f _{ACLK} /32 no LCD connected (see Note 2) T _A = 25°C | 2.2 V | | 3.8 | | μA |
| f _{LCD} | LCD frequency | | | | | 1.1 | kHz |
| V _{LCD} | LCD voltage | VLCDx = 0000 | | | VCC | | V |
| V _{LCD} | LCD voltage | VLCDx = 0001 | | | 2.50 | | V |
| V _{LCD} | LCD voltage | VLCDx = 0010 | | | 2.56 | | V |
| V _{LCD} | LCD voltage | VLCDx = 0011 | | | 2.61 | | V |
| V _{LCD} | LCD voltage | VLCDx = 0100 | | | 2.67 | | V |
| V _{LCD} | LCD voltage | VLCDx = 0101 | | | 2.72 | | V |
| V _{LCD} | LCD voltage | VLCDx = 0110 | | | 2.78 | | V |
| V _{LCD} | LCD voltage | VLCDx = 0111 | | | 2.83 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1000 | | | 2.89 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1001 | | | 2.94 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1010 | | | 3.00 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1011 | | | 3.05 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1100 | | | 3.11 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1101 | | | 3.16 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1110 | | | 3.22 | | V |
| V _{LCD} | LCD voltage | VLCDx = 1111 | | 3.12 | 3.27 | 3.42 | V |
| R _{LCD} | LCD Driver Output impedance | V _{LCD} = 3V; LCDCPEN = 1; VLCDx = 1000, I _{LOAD} = ±10μA | 2.2 V | | | 10 | kΩ |

NOTES: 1. Enabling the internal charge pump with an external capacitor smaller than the minimum specified might damage the device.
2. Connecting an actual display will increase the current consumption depending on the size of the LCD.


Workaround:
None

Detailed Bug Description (continued)

PORT6 PORT6 - Bug description:

Module: Port 2, P2.0 module function

In addition to GPIO and LCD functionality, P2.0 also has Timer_A3 module output capability. When P2SEL.0 = 1 and P2DIR.0 = 1, P2.0 becomes a TA2 output.



Note: x = 0
y = 13

| PIN NAME (P2.X) | X | FUNCTION | CONTROL BITS / SIGNALS | | |
|-----------------|---|-------------------|------------------------|---------|--------|
| | | | P2DIR.x | P2SEL.x | LCDS12 |
| P2.0/S13/TA2 | 0 | P2.0 Input/Output | 0/1 | 0 | 0 |
| | | N/A | 0 | 1 | 0 |
| | | Timer_A3.TA2 | 1 | 1 | 0 |
| | | S13 | X | X | 1 |

Workaround:
N/A

Detailed Bug Description (continued)

SDA1 SDA1 - Bug description:

Module: SD16_A, Buffer always on

Input buffer continues to consume current after being disabled.
The corresponding specification is shown below:

SD16_A, power supply and recommended operating conditions

| PARAMETER | TEST CONDITIONS | V _{CC} | MIN | TYP | MAX | UNIT | |
|-------------------|--|--|-----------------------------|------|------|------|-----|
| A _{VCC} | Analog supply voltage A _{VCC} = DV _{CC} A _{VSS} = DV _{SS} = 0V | | 2.5 | | 3.6 | V | |
| I _{SD16} | Analog supply current including internal reference | SD16LP = 0, f _{SD16} = 1 MHz, SD16OSR = 256 | SD16BUFx = 00; GAIN: 1,2 | 3 V | 850 | 1200 | μA |
| | | | SD16BUFx = 00; GAIN: 4,8,16 | 3 V | 900 | 1250 | |
| | | | SD16BUFx = 00; GAIN: 32 | 3 V | 1300 | 1800 | |
| | | SD16LP = 1, f _{SD16} = 0.5 MHz, SD16OSR = 256 | SD16BUFx = 00; GAIN: 1 | 3 V | 800 | 1050 | |
| | | | SD16BUFx = 00; GAIN: 32 | 3 V | 850 | 1200 | |
| | | SD16LP = 0, f _{SD16} = 1 MHz, SD16OSR = 256 | SD16BUFx = 01; GAIN: 1 | 3 V | 850 | | |
| | | | SD16BUFx = 10; GAIN: 1 | 3 V | 1130 | | |
| | SD16BUFx = 11; GAIN: 1 | 3 V | 1130 | | | | |
| f _{SD16} | Analog front-end input clock frequency | SD16LP = 0 (Low power mode disabled) | 3 V | 0.03 | 1 | 1.1 | MHz |
| | | SD16LP = 1 (Low power mode enabled) | 3 V | 0.03 | 0.5 | | |

Workaround:
None

SDA3 SDA3 - Bug description:

Module: SD16_A, the interrupt delay function can result in incorrect conversion data

The interrupt delay operation can result in incorrect conversion data when
SD16INTDLYx = 01, 10 or 11.

Workaround:
Use SD16INTDLYx = 00 setting (Interrupt generated after 4th conversion). This will apply to the first conversion in Continuous mode and to each conversion in Single mode.

Detailed Bug Description (continued)

TA12 TA12 - Bug description:

Module: TimerA, Function: Interrupt is lost (slow ACLK)

TimerA counter is running with slow clock (external TACLK or ACLK) compared to MCLK. The compare mode is selected for the capture/compare channel and the CCRx register is incremented by 1 with the occurring compare interrupt (if TAR = CCRx).

Due to the fast MCLK the CCRx register increment ($CCR_x = CCR_x + 1$) happens before the TimerA counter has incremented again. Therefore the next compare interrupt should happen at once with the next TimerA counter increment (if $TAR = CCR_x + 1$). This interrupt gets lost.

Workaround:

Switch capture/compare mode to capture mode before the CCRx register increment. Switch back to compare mode afterwards.

TA16 TA16 - Bug description:

Module: TimerA, Function: First increment of TAR erroneous when IDx > 00

The first increment of TAR after any timer clear event (POR/TACLR) happens immediately following the first positive edge of the selected clock source (INCLK, SMCLK, ACLK or TACLK). This is independent of the clock input divider settings (ID0, ID1). All following TAR increments are performed correctly with the selected IDx settings.

Workaround:

None

WDG2 WDG2 - Bug description:

If a key violation is caused by incorrectly accessing a flash control register, the watchdog interrupt flag is set in addition to a correctly generated PUC.

Workaround:

None

Appendix: Prior Versions

None

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

| Products | | Applications | |
|-----------------------|--|---------------------|--|
| Amplifiers | amplifier.ti.com | Audio | www.ti.com/audio |
| Data Converters | dataconverter.ti.com | Automotive | www.ti.com/automotive |
| DSP | dsp.ti.com | Broadband | www.ti.com/broadband |
| Interface | interface.ti.com | Digital Control | www.ti.com/digitalcontrol |
| Logic | logic.ti.com | Military | www.ti.com/military |
| Power Mgmt | power.ti.com | Optical Networking | www.ti.com/opticalnetwork |
| Microcontrollers | microcontroller.ti.com | Security | www.ti.com/security |
| RFID | www.ti-rfid.com | Telephony | www.ti.com/telephony |
| Low Power Wireless | www.ti.com/lpw | Video & Imaging | www.ti.com/video |
| | | Wireless | www.ti.com/wireless |

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2007, Texas Instruments Incorporated